







Baureihe 86 additional sets assembly instructions




compressor












water feeding pump








Electric equipment



















grease pump + interior






























armature



























1 - PE spacers



q - complete left and right sides together





S

